

Datasheet Correction: AD converter

We would like to inform customers the corrections of the following datasheets. If you have any questions or require any further information, please contact your local sales office.

1. Products

TMPM330FDFG, TMPM330FYFG, TMPM330FWFG
TMPM332FWUG
TMPM333FDFG, TMPM333FYFG, TMPM333FWFG
TMPM361F10FG, TMPM362F10FG, TMPM363F10FG, TMPM364F10FG

2. Correction

The datasheet of these products did not contain below cautions of AD converter.

CAUTION

Please keep the following restrictions and use.

(1) Do not change clock gear during AD converting. And condition is below.

Gear ratio down from 1 :1 to 1 :N (N=2,4,8,16)

(2) Keep frequency ratio between f_{ADCLK} and f_{SYS} as below condition.

$f_{ADCLK} \div f_{SYS} < 9.75$ times